

Under Review Notification

Raised By: VANESSA MOREL

Date: 19.08.27

Product #: DART TOOLING EUROCOPTER

Product Name: EXTRACTOR

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Re-Work Stock	PP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
RBE105-14181W4	RBE105-14181W4 REV B	Y	Y	N	Y	N	N	N	19-874	SEE BELOW
RBE105-14181W4-1	RBE105-14181W4 REV B	Y	Y	N	Y	N	N	N	19-874	SEE BELOW
RBE105-14181W4-3	RBE105-14181W4 REV B	Y	Y	N	Y	N	N	N	19-874	SEE BELOW
RBE105-14181W4-5	RBE105-14181W4 REV B	Y	Y	N	Y	N	N	N	19-874	SEE BELOW
RBE105-14181W4-7	RBE105-14181W4 REV B	Y	Y	N	Y	N	N	N	19-874	SEE BELOW
RBE105-14181W4-15	RBE105-14181W4 REV B	Y	Y	N	Y	N	N	N	19-874	SEE BELOW
RBE105-14181W4-17	RBE105-14181W4 REV B	Y	Y	N	Y	N	N	N	19-874	SEE BELOW

Description of Issue:

RBE105-14181W4 ; TOOL DON'T FIT ON AIRCRAFT, PARTS LISTED HAVE WRONG DIMENSIONS, CUSTOMER GOING TO SEND US THE OEM TOOL FOR MORE INVESTIGATION

RBE105-14181W4-1 : STOCK NEED TO BE SCRAPPED

RBE105-14181W4-3 : STOCK NEED TO BE SCRAPPED

RBE105-14181W4-5 : STOCK NEED TO BE SCRAPPED

RBE105-14181W4-7 : STOCK NEED TO BE SCRAPPED

RBE105-14181W4-15 : STOCK NEED TO BE SCRAPPED

RBE105-14181W4-17 : STOCK NEED TO BE SCRAPPED

Distribution:

VP Operations

Director of Operations

Director Quality Assurance

QC Coordinator

Director of Engineering

Chief Engineer

Engineering Project Managers

Engineering Clerk

Customer Support Manager

Production Engineers

Production Planners

Purchasing Manager

Technical Support

Product Manager - Solutions Provider

Supply Chain Director / Senior Buyer

Marketing Eugene